Blue

I. GENERATOR (Generator completes I a-f)

a. Generator's US EPA ID Number	b. Manifest Document Number	c. Page 1 of
NA	08-21-15-3241	1

d. Generator's Name and Location:	e. Generator's Mailing Address:
Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone:(606) 776-9030	Same g. Phone:
If owner of the generating facility differs from the generator, provide: h. Owner's Name:	i. Owner's Phone No.. Same

j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No.	m. Containers Type	n. Total Quantity	o. Unit Wt/Vol
Y 4002151	6/14/2017	Exploration and Production Soil and Debris	1	VB	1	25 Yds

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print)	q. Signature	r. Date
Gary Hoskins		7-28-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: Salyer Branch Transport 5+115 Truck 5+160 Trailer

b. Phone:

c. Driver Name (Print)	d. Signature	e. Date
Donald Lowery IV	Donald Lowery	8-27-15

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address:	c. US EPA Number	d. Discrepancy Indication Space:
Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239	NA	

I herby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.

e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:	c. Responsible Agency Name and Address:
b. Phone:	d. Phone:

e. Special Handling Instructions and Additional Information:
NA

f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable

OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

NA		
g. Operator's Name and Title (Print)	h. Signature	i. Date

*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both

Both Lowery Blowery 8/27/15

White

I. GENERATOR (Generator completes a-f)

a. Generator's US EPA ID Number	b. Manifest Document Number	c. Page 1 of
NA	08-21-15-2	1

d. Generator's Name and Location:	e. Generator's Mailing Address:
Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone:(606) 776-9030	Same g. Phone:
If owner of the generating facility differs from the generator, provide:	
h. Owner's Name:	i. Owner's Phone No.. Same

j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No.	m. Containers Type	n. Total Quantity	o. Unit Wt/Vol
Y400215	6/14/2017	Exploration and Production Soil and Debris	1	VB	1	25 Yds

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print)	q. Signature	r. Date
Cory Hosken		7-28-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address:

FF 168

b. Phone: Stryker Peterich Transport

c. Driver Name (Print)	d. Signature	e. Date
Rodney Smith	Rodney Smith	8/27/15

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address: Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239	c. US EPA Number NA	d. Discrepancy Indication Space:

I herby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.

e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:	c. Responsible Agency Name and Address:
b. Phone:	d. Phone:

e. Special Handling Instructions and Additional Information:
NA

f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable

OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

g. Operator's Name and Title (Print)	h. Signature	i. Date
NA		

*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both

Beth Lowery Blowery 8/27/15

White Truck

Waste is NOT asbestos waste (Generator's Section)

I. GENERATOR (Generator completes Ia-r)

a. Generator's US EPA ID Number	b. Manifest Document Number	c. Page 1 of
NA	08-23-15-2	1

d. Generator's Name and Location:	e. Generator's Mailing Address:
Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone:(606) 776-9030	Same g. Phone:
If owner of the generating facility differs from the generator, provide: h. Owner's Name:	i. Owner's Phone No.: Same

j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No.	m. Containers Type	n. Total Quantity	o. Unit Wt/Vol
Y4002151	6/14/2017	Exploration and Production Soil and Debris	1	VB	1	25 Yds

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print)	q. Signature	r. Date
Gary Hoskins		7-28-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address:
A Sauces Branch Transport
Load # 1
Trailer # 170
b. Phone:

c. Driver Name (Print)	d. Signature	e. Date
Rodney Smith	Rodney Smith	8/31/15

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address:	c. US EPA Number	d. Discrepancy Indication Space:
Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239	NA	

I herby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.

e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:	c. Responsible Agency Name and Address:
b. Phone:	d. Phone:

e. Special Handling Instructions and Additional Information:
NA

f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable

OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

g. Operator's Name and Title (Print)	h. Signature	i. Date
NA		

*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both

Both Initials 8/31/15

Blue truck

I. GENERATOR (Generator completes Ia-r)

a. Generator's US EPA ID Number	b. Manifest Document Number	c. Page 1 of
NA	541 8-19-15-1	1

d. Generator's Name and Location:	e. Generator's Mailing Address:
Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone:(606) 776-9030	Same g. Phone:
If owner of the generating facility differs from the generator, provide: h. Owner's Name:	i. Owner's Phone No.: Same

j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No.	m. Containers Type	n. Total Quantity	o. Unit Wt/Vol
Y4002151	6/14/2017	Exploration and Production Soil and Debris	1	VB	1	25 Yds

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print)	q. Signature	r. Date
Craig Hoskins		7-28-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: S&J Fox Branch Transport Truck 5th/S- Trailers 1/60

b. Phone:

c. Driver Name (Print)	d. Signature	e. Date
Donald Dowell II	Donald Dowell	8-21-15

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address:	c. US EPA Number	d. Discrepancy Indication Space:
Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239	NA	

I herby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.

e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:	c. Responsible Agency Name and Address:
b. Phone:	d. Phone:

e. Special Handling Instructions and Additional Information:
NA

f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable

OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

g. Operator's Name and Title (Print)	h. Signature	i. Date
NA		

*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both

Beth Lowery Blowery 8/21/15

Waste is NOT asbestos waste or Refer to Section ...

I. GENERATOR (Generator completes Ia-r)

a. Generator's US EPA ID Number	b. Manifest Document Number	c. Page 1 of
NA	SAI 8-13-15-3	1

d. Generator's Name and Location:	e. Generator's Mailing Address:
Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone:(606) 776-9030	Same g. Phone:
If owner of the generating facility differs from the generator, provide: h. Owner's Name:	i. Owner's Phone No.: Same

j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No.	m. Containers Type	n. Total Quantity	o. Unit Wt/Vol
Y4002151	6/14/2017	Exploration and Production Soil and Debris	1	VB	1	25 Yds

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print)	q. Signature	r. Date
Cory Hoskins		7-28-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: Salyer Brandt Transport + Truck 115 Trailor

b. Phone:

c. Driver Name (Print)	d. Signature	e. Date
Donald Lovely	Donald Lovely	8-18-15

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address:	c. US EPA Number	d. Discrepancy Indication Space:
Blue Ridge CA-D-F-17 2700 Winchester Rd Irvine, Ky	NA	

b. Phone: 606 928 0239

I herby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.

e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:	c. Responsible Agency Name and Address:
b. Phone:	d. Phone:
e. Special Handling Instructions and Additional Information: NA	

f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable

OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

g. Operator's Name and Title (Print)	h. Signature	i. Date
NA		

*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both

Both lowery Blowery 8/18/15

I. GENERATOR (Generator completes Ia-r)

a. Generator's US EPA ID Number	b. Manifest Document Number	c. Page 1 of
NA	8-11-15-2 SA1	1

d. Generator's Name and Location:	e. Generator's Mailing Address:
Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone:(606) 776-9030	Same g. Phone:
If owner of the generating facility differs from the generator, provide: h. Owner's Name:	i. Owner's Phone No.: Same

j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No.	m. Containers Type	n. Total Quantity	o. Unit Wt/Vol
Y4002151	6/14/2017	Exploration and Production Soil and Debris	1	VB	1	25 Yds

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print)	q. Signature	r. Date
Cary Hoskins		7-28-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: Salyer Branch Transport Truck 1115 Trailer 1025 & 170

b. Phone:

c. Driver Name (Print)	d. Signature	e. Date
Donald Lovely	Donald Lovely	8-17-15

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address:	c. US EPA Number	d. Discrepancy Indication Space:
Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239	NA	

I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.

e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:	c. Responsible Agency Name and Address:
b. Phone:	d. Phone:

e. Special Handling Instructions and Additional Information:
NA

f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable

OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

g. Operator's Name and Title (Print)	h. Signature	i. Date
NA		

*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both

8-17-15

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. Nonhazardous

Manifest Document No. 00878

2. Page 1 of

3. Generator's Name and Mailing Address
Raymond Bunner
168 AFR OR
Fairmont WV

4. Generator's Phone (606) 776 9030

5. Transporter 1 Company Name: Mountain States Environmental

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 7408642137

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Blue Ridge Landfill
2700 Winchester Rd
Irvine Ky

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606 9280239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Exploration and Production Soil & Debris	001	VB TT		
b. Box # V10				
c. Y4002151				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

GENERATOR

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Agent for Generator Raymond Bunner

Signature: Raymond Bunner

Date: Month 11 Day 13 Year 15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: KEVIN LUCAS

Signature: Kevin Lucas

Date: Month 11 Day 16 Year 15

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name:

Signature:

Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: K. Kelly

Signature:

Date: Month 11 Day 16 Year 15

NON-HAZARDOUS WASTE

F-14 © 2002 LABELMASTER® (800) 621-5808 www.labelmaster.com PRINTED ON RECYCLED PAPER PRINTED WITH SOY INK

Rev. 3/95

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. Non hazardous

Manifest Document No. 00885

2. Page 1 of

3. Generator's Name and Mailing Address
Fairmont Shine
168 AFR DR
Fairmont WV

4. Generator's Phone (606) 776 9030

5. Transporter 1 Company Name: Mountain States Environmental

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740 864 2137

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Blue Ridge Landfill
2700 Winchester Rd
Irvine Ky

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606 928 0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Exploration and Production Soil & Debris	001	VB TT		
b. Box # V13				
c. Y4002151				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: agent for Generator Raymond Burner
Signature: Raymond Burner
Date: Month 11 Day 13 Year 15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Russ Courtney
Signature: Russ Courtney
Date: Month 11 Day 16 Year 15

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name:
Signature:
Date: Month 11 Day 16 Year 15

NON-HAZARDOUS WASTE

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

Please print or type. (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. Non hazardous

Manifest Document No. 00883

2. Page 1 of

GENERATOR

3. Generator's Name and Mailing Address
Fairmont Office
168 AFR Dr
Fairmont WV

4. Generator's Phone (606) 776-9030

5. Transporter 1 Company Name: Mountain States Environmental

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740 864 2131

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Blue Ridge Landfill
2700 Winchester Rd
Irvine KY

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606 928 6239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Exploration and Production Soil & Debris	001	VB TT		
b. Box # V16				
c.				
d.				

G. Additional Descriptions for Materials Listed Above
Y400151

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: agent for Generator Raymond Bunner
Signature: Raymond Bunner
Date: Month 11 Day 12 Year 15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ~~agent for General~~ Jeremy Scott
Signature:
Date: Month 11 Day 13 Year 15

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Tim Kth
Signature:
Date: Month 11 Day 13 Year 15

F-14 © 2002 LABELMASTER® (800) 621-5808 www.labelmaster.com PRINTED ON RECYCLED PAPER PRINTED WITH

Rev. 3/95

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. Non hazardous

Manifest Document No. 00884

2. Page 1 of

3. Generator's Name and Mailing Address
Fairmont Office
168 AFK Dr
Fairmont WV

4. Generator's Phone (606) 776-9030

5. Transporter 1 Company Name: Mountain States Environmental

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740 864 2157

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Blue Ridge Landfill
2700 Winchester Rd
Irvine KY

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606 928 0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Exploration and Production Soil & Debris	001	VB TT		
b. Box # V5				
c. Y 400251				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Cody Rumage | Signature | Date: Month 11 Day 12 Year 15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Raymond Bunner | Signature: Raymond Bunner | Date: Month 11 Day 12 Year 15

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Tim Roth | Signature | Date: Month 11 Day 13 Year 15

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type — form designed for use on elite (12 pitch) typewriter

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. Nonhazardous

Manifest Document No. 00880

2. Page 1 of

3. Generator's Name and Mailing Address
Fairmont Marine Processing
468 AFR Dr
Fairmont WV

4. Generator's Phone (606) 776 9030

5. Transporter 1 Company Name: Mountain States Environmental

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740 864 2137

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Blue Ridge Landfill
2700 Winchester Rd
Irvine Ky

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606 928 0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Exploration and Production Soil & Debris	001	VB TT		
b. Box # V 8				
c. # Y4002151				
d.				

GENERATOR

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

NON-HAZARDOUS WASTE

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: agent for Generator Raymond Burns

Signature: Raymond Burns

Date: Month 11 Day 12 Year 15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Kevin Lucas

Signature: Kevin Lucas

Date: Month 11 Day 12 Year 15

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Tim Rah

Signature: Tim Rah

Date: Month 11 Day 12 Year 15

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. Nonhazardous

Manifest Document No. 00832

2. Page 1 of

3. Generator's Name and Mailing Address
Fairmont Brine
168 AFR Dr
Fairmont WV
4. Generator's Phone (606) 776 4030

5. Transporter 1 Company Name: Mountain States Environmental

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 7408642137

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Blue Ridge Landfill
2700 Winchester Rd
Irvine Ky

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606 928 0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Exploration and Production Soil & Debris	001	VB TT		
b. Box # V10				
c. # Y4002151				
d.				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: Cody Rumsey — Signature — Date: Month 11 Day 11 Year 15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Raymond Bunner — Signature: Raymond Bunner — Date: Month 11 Day 11 Year 15

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name: Russ Courtney — Signature — Date: Month 11 Day 12 Year 15

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Kim Ruth — Signature — Date: Month 11 Day 12 Year 15

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. NON HAZARDOUS

Manifest Document No. 00875 | 2. Page 1 of

3. Generator's Name and Mailing Address
FAIRMONT BRINE
168 AFR DR.
FAIRMONT W.V.

4. Generator's Phone (304) 776-9030

JK#

5. Transporter 1 Company Name: MOUNTAIN STATES ENV.

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740-864-2137

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
BLUE RIDGE LANDFILL
2700 WINCHESTER RD.
IRVINE K.Y.

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606-928-0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. EXPLORATION AND PRODUCTION SANDS & DEBRIS				
b. BOX # V 16				
c.				
d. Y4002151				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name	Signature	Date Month	Day	Year
agent for Generator Raymond Bunner	Raymond Bunner	11	11	15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month	Day	Year
Bill Desrosiers		11	11	15

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name	Signature	Date Month	Day	Year
		11	11	15

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. NON Haz

Manifest Document No. 00864

2. Page 1 of 1

3. Generator's Name and Mailing Address
Fairmont Brine
168 AFR Dr
Fairmont, WV
4. Generator's Phone (606) 776-9030

TR [redacted] 550

5. Transporter 1 Company Name: Mountain States Environmental
6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740-864-2137

7. Transporter 2 Company Name
8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Blue Ridge Landfill
2700 Winchester Rd
Irvine Ky
10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606-928-0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Exploration and Production Salts and Debris				
b. Box # V-15				
c.				
d. KY4002151				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

AGENT FOR GENERATOR

Printed/Typed Name: KEVIN LUCAS
Signature: Kevin Lucas
Date: Month 11 Day 6 Year 15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.
Printed/Typed Name: Kim Ruth
Signature: Kim Ruth
Date: Month 11 Day 6 Year 15

NON-HAZARDOUS WASTE

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. NON HAZARDOUS

Manifest Document No. 00870

2. Page 1 of

3. Generator's Name and Mailing Address
FAIRMONT BRINE
168 AFR DR.
FAIRMONT W.V.

4. Generator's Phone (606) 776-9030

TK 550

5. Transporter 1 Company Name
MOUNTAIN STATES ENV.

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740-864-2137

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
BLUE RIDGE LANDFILL
2700 WINCHESTER Rd.
ERVINE KY

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606-928-0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. EXPLORATION AND PRODUCTION SAND & DEBRIS				
b. BOX V-16				
c.				
d. Y4002151				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

GENERATOR

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name: KEVIN LUCAS

Signature: Kevin Lucas

Date: Month 11 Day 9 Year 13

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Date: Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name: Beth Lowry

Signature

Date: Month 11 Day 9 Year 13

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. NON HAZARDOUS

Manifest Document No. 00874

2. Page 1 of

3. Generator's Name and Mailing Address
FAIRMONT BRINE
168 AFR OR.
FAIRMONT W.V.

4. Generator's Phone (606) 776-9030

TK #

5. Transporter 1 Company Name: MOUNTAIN STATES ENV.

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740-864-2137

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
BLUE RIDGE LANDFILL
2700 WINCHESTER RD.
IRVINE K.Y.

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606-928-0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. EXPLORATION AND PRODUCTION SHNDANG DERRIS				
b. BOX # V-8				
c.				
d. Y4002151				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name	Signature	Date Month	Day	Year
KEVIN LUCAS	Kevin Lucas	11	11	15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month	Day	Year

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name	Signature	Date Month	Day	Year
KIM RAY	K. Ray	11	11	15

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. Non Haz

Manifest Document No. 00863

2. Page 1 of 1

3. Generator's Name and Mailing Address
Fairmont Brine
168 AFR Dr
Fairmont WV

4. Generator's Phone (606) 776-9030

5. Transporter 1 Company Name: Mountain States Env.

6. US EPA ID Number

A. State Transporter's ID

B. Transporter 1 Phone 740-864-2137

7. Transporter 2 Company Name

8. US EPA ID Number

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address
Blue ridge Landfill
2700 winchester Rd
Irvine Ky

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone 606-928-0239

11. WASTE DESCRIPTION	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt./Vol.
a. Exploration and Production Soil and Debris				
b. Box # 17				
c.				
d. Y4002151				

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name	Signature	Date Month	Day	Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month	Day	Year
Russ Courtney	Russ Courtney	11	4	15

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name	Signature	Date Month	Day	Year
Kim Roth	Kim Roth	11	4	15

NON-HAZARDOUS WASTE

Waste is NOT asbestos waste or Refer to Section ...

White truck

I. GENERATOR (Generator completes Ia-r)

a. Generator's US EPA ID Number	b. Manifest Document Number	c. Page 1 of
NA	8-18-15-2	1

d. Generator's Name and Location:	e. Generator's Mailing Address:
Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone:(606) 776-9030	Same g. Phone:
If owner of the generating facility differs from the generator, provide: h. Owner's Name:	i. Owner's Phone No.: Same

j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No.	m. Containers Type	n. Total Quantity	o. Unit Wt/Vol
Y4002151	6/14/2017	Exploration and Production Soil and Debris	1	VB	1	25 Yds

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print)	q. Signature	r. Date
Cory Hosky		7-28-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address:

168

b. Phone: Sellers Branch Transport

c. Driver Name (Print)	d. Signature	e. Date
Rodney Smith	Rodney Smith	8/20/15

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address: Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239	c. US EPA Number NA	d. Discrepancy Indication Space:

I herby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.

e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address: b. Phone:	c. Responsible Agency Name and Address: d. Phone:

e. Special Handling Instructions and Additional Information:
NA

f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable

OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

g. Operator's Name and Title (Print)	h. Signature	i. Date
NA		

*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both