

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>New Haz</i>		Manifest Document No. 00992		2. Page 1 of 1	
		3. Generator's Name and Mailing Address <i>Green Hunter Mills Hunter SR 33 Portland OH</i>					
4. Generator's Phone ()				<i>Mills Hunter</i>			
5. Transporter 1 Company Name <i>Mountain States Env.</i>		6. US EPA ID Number		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone <i>740-864-2137</i>			
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky</i>		10. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone <i>606-723-5552</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No.	Type		
a. <i>used Filters + Debris</i>							
b. <i>Box # C20-25</i>							
c.							
d. <i>Y4002158</i>							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>Carol</i>				Signature <i>Carol</i>		Date Month <i>9</i> Day <i>22</i> Year <i>15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Charlie Dean</i>		Date Month <i>7</i> Day <i>2</i> Year <i>15</i>	
Printed/Typed Name <i>Charlie Dean</i>				Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>Beth Lowery</i>				Signature <i>Lowery</i>		Date Month <i>7</i> Day <i>10</i> Year <i>15</i>	

NON-HAZARDOUS WASTE

TRANSPORTER

FACILITY



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Non hazardous</i>		Manifest Document No. 00830		2. Page 1 of	
3. Generator's Name and Mailing Address <i>Green Hunter SR7 New Matamoras Oh 45767</i>							
4. Generator's Phone ()							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
				B. Transporter 1 Phone <i>740 864 2137</i>			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill 2700 Winchester Rd Irvine Ky</i>		10. US EPA ID Number		E. State Facility's ID			
				F. Facility's Phone <i>606 928 0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No.	Type		
a. <i>Filter Sludge</i>				<i>001</i>	<i>TT</i>		
b. <i>Truck #550</i>							
c. <i>Y4002160</i>							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>Raymond Bunner</i>				Signature <i>Raymond Bunner</i>		Date Month <i>11</i> Day <i>19</i> Year <i>15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Derek Wright</i>		Date Month <i>11</i> Day <i>20</i> Year <i>15</i>	
Printed/Typed Name <i>Derek Wright</i>				Signature		Date Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date Month Day Year	
Printed/Typed Name				Signature		Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>Kim Smith</i>				Signature <i>Kim Smith</i>		Date Month <i>11</i> Day <i>20</i> Year <i>15</i>	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Non-Hazardous</i>		Manifest Document No. 00882		2. Page 1 of 1	
3. Generator's Name and Mailing Address <i>Green Hunter Ellenboro NJ</i>							
4. Generator's Phone ()							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone <i>740-864-2137</i>			
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill 2700 WICKLESBURG RD IRVING NY</i>		10. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone <i>606-928-0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No.	Type		
a. <i>Used Filters</i>							
b. <i>Box # 6 HES 07</i>							
c. <i>14002157</i>							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name				Signature		Date	
						Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date			
Printed/Typed Name		Signature		Month		Day Year	
<i>Bill Desrosiers</i>		<i>Bill Desrosiers</i>		<i>11</i>		<i>12 15</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date			
Printed/Typed Name		Signature		Month		Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date	
<i>Tom Rahn</i>				<i>Tom Rahn</i>		Month Day Year	
						<i>11 13 15</i>	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Non hazardous</i>		Manifest Document No. 00879		2. Page 1 of	
3. Generator's Name and Mailing Address <i>Mills Hunter 53610 +WP RD 206 Portland OH</i>							
4. Generator's Phone ()							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone <i>740 864 2157</i>			
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill 2700 Winchester RD Cabinus KY</i>		10. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No.	Type		
a. <i>Used filters</i>				<i>001</i>	<i>CM</i>		
b. <i>Box Chesor</i>							
c.							
d. <i>Y4002159</i>							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name				Signature		Date	
						Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name <i>Russ Courtney</i>				<i>Russ Courtney</i>		<i>11/11/15</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name						Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>Kim Roth</i>				Signature <i>Kim Roth</i>		Date <i>11/11/15</i>	

NON-HAZARDOUS WASTE



NON-HAZARDOUS WASTE MANIFEST

(Form designed for use on ellipse (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST 1. Generator's US EPA ID No. <i>Non hazardous</i>		Manifest Document No. 00849		2. Page 1 of	
3. Generator's Name and Mailing Address <i>Green Mountain</i> SR 7 New Matamoras OH 45767		4. Generator's Phone () _____		5. Transporter 1 Company Name <i>Mountain States Environments</i>	
6. Transporter 1 US EPA ID Number _____		7. Transporter 2 Company Name _____		8. Transporter 2 US EPA ID Number _____	
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill</i> 8700 Winchester Rd Irvine KY		10. US EPA ID Number _____		11. Facility's Phone _____	
12. Containers No. Type _____		13. Total Quantity _____		14. Unit _____	
15. Waste Description a. b. c. d.		16. Additional Descriptions for Materials Listed Above _____		17. Handling Codes for Wastes Listed Above _____	
18. Generator's Certification: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name <i>James H. Hester</i>		Signature <i>James H. Hester</i>		Date 11/19/15	
Printed/Typed Name <i>Deborah Wright</i>		Signature <i>Deborah Wright</i>		Date 11/19/15	
Printed/Typed Name <i>Russ Gaudin</i>		Signature <i>Russ Gaudin</i>		Date 11/20/15	
19. Discrepancy Indication Space _____					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19. _____					
Printed/Typed Name <i>Mark Smith</i>		Signature <i>Mark Smith</i>		Date 11/26/15	

NON-HAZARDOUS WASTE

BO-123456789





UTILIZATION

RECYCLING

Y 4002162

Goff-USTS
(Nuverra Environmental Resources)

Non-Hazardous Waste Manifest



Non-Hazardous Waste Manifest		1. Generator's Pa. DEP ID No.		2. Page 1 of 1		Manifest Document No. Goff USTS-AM-001					
3. Generator's Name and Mailing Address Goff-USTS 9350 East Pike Norwich, OH 43767											
4. Generator's Phone Leo Gismondi (724) 840-1012											
5. Transporter 1 Company Name Buckeye Water Service Company				6. US EPA ID Number		A. Transporter's Phone (740) 826-7674					
7. Transporter 2 Company Name				8. US EPA ID Number		B. Transporter's Phone					
9. Designated Facility Name and Site Address Blue Ridge Landfill 2700 Winchester Road Irvine, KY 40336				10. US EPA ID Number/ DEP ID No.		C. Facility Phone					
11. Waste Shipping Name and Description						12. Containers		13. Total		14. Unit	
						No. Type		Quantity		Wt/Vol	
A. Filters and Cartridges Box# 9913005						1		RO		100%	
B.											
C.											
D. Additional Descriptions for Material Listed Above						E. Handling Code for Waste Listed Above					
15. Special Handling Instructions and Additional Information											
16. Generator Certification: I certify that the materials described above on this manifest are not subject to Federal Regulations for reporting proper disposal of Hazardous Waste.											
Printed/Typed name Brian Kirkpatrick				Signature 		Month 12		Day 16		Year 2015	
17. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed name Danny R. Valentine				Signature 		Month 12		Day 16		Year 15	
18. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed name Lee Tharp				Signature 		Month 12		Day 17		Year 15	
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in item 19.											
Printed/Typed name 				Signature 		Month 12		Day 17		Year 15	

G
E
N
E
R
A
T
O
R



T
R
A
N
S
P
O
R
T
E
R

F
A
C
I
L
I
T
Y

Nuverra Environmental Solutions

G E N E R A T O R T R A N S P O R T E R	Non-Hazardous Waste Manifest	1. Generator's Pa. DEP ID No.	2. Page 1 of 1		Manifest Document No. Nuverra-AM-001		
	3. Generator's Name and Mailing Address Nuverra Environmental Solutions (Pander R&P (SWIW # 15 & #16) 1 & 2) 5310 State Route 5 Newton Falls, OH 44444						
	4. Generator's Phone Leo Gismondi (724) 840-1012						
	5. Transporter 1 Company Name Buckeye Water Service Company		6. US EPA ID Number		A. Transporter's Phone (740) 826-7674		
	7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter's Phone		
	9. Designated Facility Name and Site Address Blue Ridge Landfill 2700 Winchester Road Irvine, KY 40336		10. US EPA ID Number/ DEP ID No.		C. Facility Phone Contact		
	11. Waste Shipping Name and Description				12. Containers		13. Total
					No. Type		Quantity
	A. soil/gravel Box# 79				1 RO		100%
	B.						
A N T H O N Y	C.						
	D. Additional Descriptions for Material Listed Above				E. Handling Code for Waste Listed Above		
	15. Special Handling Instructions and Additional Information 44-002162						
	16. Generator Certification: I certify that the materials described above on this manifest are not subject to Federal Regulations for reporting proper disposal of Hazardous Waste.						
	Printed/Typed name Bona Kokporok		Signature 		Month 1	Day 28	Year 2016
	17. Transporter 1 Acknowledgement of Receipt of Materials						
	Printed/Typed name CARL LEE THARP		Signature 		Month 2	Day 3	Year 16
	18. Transporter 1 Acknowledgement of Receipt of Materials						
	Printed/Typed name JO ETTA MCKIN		Signature 		Month 1	Day 28	Year 16
	19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in item 19.							
Printed/Typed name Kim Ruth		Signature 		Month 2	Day 3	Year 16	

74002162

Non-Hazardous Waste Manifest		1. Generator's Pa. DEP ID No.		2. Page 1 of 1		Manifest Document No. Goff USTS-AM-001			
3. Generator's Name and Mailing Address Goff-USTS 9350 East Pike Norwich, OH 43767									
4. Generator's Phone Leo Gismondi (724) 840-1012									
5. Transporter 1 Company Name Buckeye Water Service Company				6. US EPA ID Number		A. Transporter's Phone (740) 826-7674			
7. Transporter 2 Company Name				8. US EPA ID Number		B. Transporter's Phone			
9. Designated Facility Name and Site Address Blue Ridge Landfill 2700 Winchester Road Irvine, KY 40336				10. US EPA ID Number/ DEP ID No.		C. Facility Phone			
11. Waste Shipping Name and Description						Contact			
A. Filters and Cartridges Box# 9913006						12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	
						1	RO	100%	Ton
B.									
C.									
D. Additional Descriptions for Material Listed Above						E. Handling Code for Waste Listed Above			
15. Special Handling Instructions and Additional Information									
16. Generator Certification: I certify that the materials described above on this manifest are not subject to Federal Regulations for reporting proper disposal of Hazardous Waste.									
Printed/Typed name Brian Kirkpatrick		Signature 		Month 12		Day 16		Year 2015	
17. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed name Denny R. Valenti		Signature 		Month 12		Day 16		Year 15	
18. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed name Lee Tharp		Signature 		Month 12		Day 18		Year 15	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in item 19.									
Printed/Typed name 11261		Signature 		Month 12		Day 18		Year 15	

G
E
N
E
R
A
T
O
R

T
R
A
N
S
P
O
R
T
E
R

F
A
C
I
L
I
T
Y

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST 1. Generator's US EPA ID No.		Manifest Document No. 5451		2. Page 1 of	
3. Generator's Name and Mailing Address Mills Hunter 56610 kwp rd 706 Portland OH 45770					
4. Generator's Phone ()					
5. Transporter 1 Company Name Munich's Environmental					
6. US EPA ID Number					
7. Transporter 2 Company Name					
8. US EPA ID Number					
9. Designated Facility Name and Site Address Blue Ridge Landfill 8700 Winchester RD Louisville KY					
10. US EPA ID Number					
11. WASTE DESCRIPTION Used Cylinders & Debris					
12. Containers No. Type					
13. Total Quantity 3.51					
14. Unit WT/VOL					
15. Special Handling Instructions and Additional Information Box 6465 00					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Date					
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Date					
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Date Month Day Year					
Signature Printed/Typed Name					

NON-HAZARDOUS WASTE

FORM 100-202-1

UTILIZATION



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. NON-HAZARDOUS		Manifest Document No. 00936		2. Page 1 of 1	
3. Generator's Name and Mailing Address GREEN HUNTER NEW MATAMORAS 28407 STATE ROUTE 7 MARIETTA, OH 43750				TRUCK 550			
4. Generator's Phone (740) 373-9511							
5. Transporter 1 Company Name MOUNTAIN STATES ENVIRONMENTAL		6. US EPA ID Number		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 740-864-2137			
				C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address BLUE RIDGE LANDFILL 2700 WINCHESTER R.D. IRVINE, KY		10. US EPA ID Number		E. State Facility's ID			
				F. Facility's Phone 800-888-3244			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		Unit Wt./Vol.	
a. TANK BOTTOM SLUDGE FOR SOLIDIFICATION				001 TT			
b.							
c.							
d. Y4002160							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name AGENT FOR GENERATOR DARREN L. GRUBBS				Signature <i>Darren L. Grubbs</i>		Date Month Day Year 8 18 15	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Tony Pethel		Signature <i>Tony Pethel</i>	
						Date Month Day Year 8 19 15	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
						Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Beth Lowery				Signature <i>Beth Lowery</i>		Date Month Day Year	

NON-HAZARDOUS WASTE



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST 1. Generator's US EPA ID No. NON-HAZARDOUS		3. Generator's Name and Mailing Address GREEN HUNTER NEW MATERIALS 28407 STATE ROUTE 7 MARZETTA, OHIO 45750		4. Generator's Phone () 740-373-9511		5. Transporter 1 Company Name MOUNTAIN STATES ENVIRONMENTAL		6. US EPA ID Number		7. Transporter 2 Company Name		8. US EPA ID Number		9. Designated Facility Name and Site Address BLUE RIDGE LANDFILL 2700 WINCHESTER RD. ZEVANSKY		10. US EPA ID Number		11. WASTE DESCRIPTION TANK BOTTOM SLUDGE FOR SOLIDIFICATION 001 TP		12. Containers No. Type		13. Total Quantity 14. Unit TRUCK 690		15. Special Handling Instructions and Additional Information White truck		16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.		17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name AGENT FOR GENERATION DANNEN L GRIFFIN Signature <i>Dannen Griffin</i> Date 8/15/15		18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name CHARLIE BROWN Signature <i>Charlie Brown</i> Date 8/17/15		19. Discrepancy Indication Space		20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.		Printed/Typed Name Beth Bouvier Signature <i>Beth Bouvier</i> Date 8/17/15	
--	--	--	--	--	--	---	--	---------------------	--	-------------------------------	--	---------------------	--	--	--	----------------------	--	--	--	----------------------------	--	--	--	--	--	---	--	--	--	---	--	----------------------------------	--	---	--	--	--

NON-HAZARDOUS WASTE

ROTATING

MANIFEST

UTIL-CAT

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on ellipse (12 pitch) typewriter)

2. Page 1 of		00981	Manifest Document No.
--------------	--	-------	-----------------------

3. Generator's Name and Mailing Address GREAT HARBOR		4. Generator's Phone ()	
5. Transporter 1 Company Name		6. US EPA ID Number	
7. Transporter 2 Company Name		8. US EPA ID Number	
9. Designated Facility Name and Site Address PACIFIC		10. US EPA ID Number	
A. State Transporter's ID		B. Transporter 1 Phone 1-800-837-8041	
C. State Transporter's ID		D. Transporter 2 Phone	
E. State Facility's ID		F. Facility's Phone	

11. WASTE DESCRIPTION				12. Containers		13. Total		14. Unit	
				No.	Type	Quantity		Wt./Vol.	
1									
2									
3									
4									
5									
6									
7									
8									
9									
10									

G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above	
---	--	---	--

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name	Signature	Date

17. Transporter 1 Acknowledgment of Receipt of Materials	Signature	Date

18. Transporter 2 Acknowledgment of Receipt of Materials	Signature	Date

19. Facility Owner or Operator Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.	Signature	Date

NON-HAZARDOUS WASTE

NON-HAZARDOUS SPECIAL WASTE & ASBESTOS MANIFEST

If waste is asbestos waste, complete Sections I, II, III and IV
If waste is NOT asbestos waste, complete Sections I, II and III

I. GENERATOR (Generator completes Ia-r)

a. Generator's US EPA ID Number
NA

b. Manifest Document Number 001-000-004
8-7-15

c. Page 1 of 1

d. Generator's Name and Location:
Cambrian Well Services
7675 East Pike
Norwich, Ohio 43767
f. Phone: (606) 776-9030

e. Generator's Mailing Address:
Same

g. Phone:

If owner of the generating facility differs from the generator, provide:

h. Owner's Name:

i. Owner's Phone No.: Same

j. Waste Profile #

k. Exp. Date

l. Waste Shipping Name and Description

m. Containers

n. Total
Quantity

o. Unit
Wt/Vol

No. Type

6/14/2017

Exploration and Production Soil and
Debris

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions, I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print)

q. Signature

r. Date 8-7-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address:

b. Phone:

c. Driver Name (Print)

d. Signature

e. Date

8/7/15

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST 1. Generator's US EPA ID No.		Manifest Document No. 00980		2. Page 1 of	
3. Generator's Name and Mailing Address GREEN HILLS		4. Generator's Phone ()		5. Transporter 1 Company Name ENV	
6. US EPA ID Number		7. Transporter 1 Company Name		8. US EPA ID Number	
9. Designated Facility Name and Site Address Waste Transfer Station		10. US EPA ID Number		11. Facility's Phone 1606 723 6552	
12. Containers		13. Total Quantity		14. Unit	
15. Waste Description		16. No.		17. Type	
18. Additional Descriptions for Materials Listed Above		19. Handling Codes for Wastes Listed Above		20. Date	
21. Special Handling Instructions and Additional Information		22. Date		23. Signature	
24. Date		25. Signature		26. Date	
27. Date		28. Signature		29. Date	
30. Date		31. Signature		32. Date	
33. Date		34. Signature		35. Date	
36. Date		37. Signature		38. Date	
39. Date		40. Signature		41. Date	
42. Date		43. Signature		44. Date	
45. Date		46. Signature		47. Date	
48. Date		49. Signature		50. Date	
51. Date		52. Signature		53. Date	
54. Date		55. Signature		56. Date	
57. Date		58. Signature		59. Date	
60. Date		61. Signature		62. Date	
63. Date		64. Signature		65. Date	
66. Date		67. Signature		68. Date	
69. Date		70. Signature		71. Date	
72. Date		73. Signature		74. Date	
75. Date		76. Signature		77. Date	
78. Date		79. Signature		80. Date	
81. Date		82. Signature		83. Date	
84. Date		85. Signature		86. Date	
87. Date		88. Signature		89. Date	
90. Date		91. Signature		92. Date	
93. Date		94. Signature		95. Date	
96. Date		97. Signature		98. Date	
99. Date		100. Signature		101. Date	
102. Date		103. Signature		104. Date	
105. Date		106. Signature		107. Date	
108. Date		109. Signature		110. Date	
111. Date		112. Signature		113. Date	
114. Date		115. Signature		116. Date	
117. Date		118. Signature		119. Date	
120. Date		121. Signature		122. Date	
123. Date		124. Signature		125. Date	
126. Date		127. Signature		128. Date	
129. Date		130. Signature		131. Date	
132. Date		133. Signature		134. Date	
135. Date		136. Signature		137. Date	
138. Date		139. Signature		140. Date	
141. Date		142. Signature		143. Date	
144. Date		145. Signature		146. Date	
147. Date		148. Signature		149. Date	
150. Date		151. Signature		152. Date	
153. Date		154. Signature		155. Date	
156. Date		157. Signature		158. Date	
159. Date		160. Signature		161. Date	
162. Date		163. Signature		164. Date	
165. Date		166. Signature		167. Date	
168. Date		169. Signature		170. Date	
171. Date		172. Signature		173. Date	
174. Date		175. Signature		176. Date	
177. Date		178. Signature		179. Date	
180. Date		181. Signature		182. Date	
183. Date		184. Signature		185. Date	
186. Date		187. Signature		188. Date	
189. Date		190. Signature		191. Date	
192. Date		193. Signature		194. Date	
195. Date		196. Signature		197. Date	
198. Date		199. Signature		200. Date	
199. Date		200. Signature		201. Date	
200. Date		201. Signature		202. Date	



NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 00979	2. Page 1 of
3. Generator's Name and Mailing Address <i>General Electric</i>				<i>TRUCK 690</i>	
4. Generator's Phone ()					
5. Transporter 1 Company Name		6. US EPA ID Number	A. State Transporter's ID		
			B. Transporter 1 Phone <i>800-864-2131</i>		
7. Transporter 2 Company Name		8. US EPA ID Number	C. State Transporter's ID		
			D. Transporter 2 Phone		
9. Designated Facility Name and Site Address		10. US EPA ID Number	E. State Facility's ID		
			F. Facility's Phone		
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt/Vol.
			No.	Type	
a. <i>DEBRIS BOYGHESID</i>					
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name			Signature		Date Month Day Year
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature		Date Month Day Year
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

NON-HAZARDOUS WASTE



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on efile (12 pitch) typewriter)

1. Generator's US EPA ID No.		Manifest Document No.	2. Page 1 of 00969
------------------------------	--	-----------------------	--------------------

3. Generator's Name and Mailing Address		4. Generator's Phone ()	
5. Transporter 1 Company Name		6. US EPA ID Number	
7. Transporter 2 Company Name		8. US EPA ID Number	
9. Designated Facility Name and Site Address		10. US EPA ID Number	

A. State Transporter's ID		B. Transporter 1 Phone	
C. State Transporter's ID		D. Transporter 2 Phone	
E. State Facility's ID		F. Facility's Phone	

11. WASTE DESCRIPTION		12. Containers		13. Total Quantity		14. Unit	
a	b	c	d	e	f	g	h

G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above	
---	--	---	--

15. Special Handling Instructions and Additional Information	
--	--

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name	Signature	Month	Day	Year
--------------------	-----------	-------	-----	------

Printed/Typed Name	Signature	Month	Day	Year
--------------------	-----------	-------	-----	------

Printed/Typed Name	Signature	Month	Day	Year
--------------------	-----------	-------	-----	------

17. Discrepancy Indication Space

18. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name	Signature	Month	Day	Year
--------------------	-----------	-------	-----	------

NON-HAZARDOUS WASTE MANIFEST

Printed on Recycled Paper (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST 1. Generator's US EPA ID No.		Manifest Document No. 00978	
3. Generator's Name and Mailing Address GREEN HUNTER 10000 620		4. Generator's Phone ()	
5. Transporter 1 Company Name Env		6. US EPA ID Number	
7. Transporter 2 Company Name		8. US EPA ID Number	
9. Designated Facility Name and Site Address 1001 CM		10. US EPA ID Number	
11. WASTE DESCRIPTION		12. Containers No. Type	
13. Total Quantity		14. Unit Wt/Vol.	
15. Special Handling Instructions and Additional Information		16. Additional Descriptions for Materials Listed Above	
17. Generator's Certification: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.		18. Handling Codes for Wastes Listed Above	

19. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.		20. Date	
Signature		Date	
21. Transporter 1 Acknowledgment of Receipt of Materials		Signature	
Date		Signature	
22. Transporter 2 Acknowledgment of Receipt of Materials		Signature	
Date		Signature	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Non-Haz</i>		Manifest Document No. 00967		2. Page 1 of	
3. Generator's Name and Mailing Address <i>GREEN HUNTER WASTE</i>				690 / Boychesol			
4. Generator's Phone (746) 756-223							
5. Transporter 1 Company Name		6. US EPA ID Number		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 1800-837-8061			
9. Designated Facility Name and Site Address		10. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
				No.	Type		
a				100	CM		
b							
c							
d							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above IN = 45,000 OUT = 38,600			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name				Signature		Date Month Day Year 8 10 15	
17. Transporter 1 Acknowledgment or Receipt of Materials				Signature		Date Month Day Year 8 10 15	
18. Transporter 2 Acknowledgment or Receipt of Materials				Signature		Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year 8 10 15	

NON-HAZARDOUS WASTE



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST 1. Generator's US EPA ID No. NON HAZ		Manifest Document No. 00965		2. Page 1 of 1	
3. Generator's Name and Mailing Address Green Hunter 3514 Marietta Rd Dexter City OH 45727					
4. Generator's Phone (410) 783-2233					
5. Transporter 1 Company Name Mountain States Env		6. US EPA ID Number		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 1800 837 8064	
9. Designated Facility Name and Site Address 10000 Ridge Road Fill Rd Wm Hunter Rd Irvine KY		10. US EPA ID Number		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 1606-723-5552	
11. WASTE DESCRIPTION				12. Containers	
				No. Type	
a. Oil Filters & Debris				200 CM	
b. 11 EPS 08					
c. 11 215.5					
d.					
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information IN = 46,200 OUT = 35,140					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name				Signature	
				Date Month Day Year 8/10/15	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
				Month Day Year 8/10/15	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
				Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year 8/10/15	



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

1. Generator's US EPA ID No. <i>Non-Haz</i>		Manifest Document No. 00967	2. Page 1 of
3. Generator's Name and Mailing Address <i>Green Hunter Water 11000 Rd Dallas TX 75127</i>		<i>690 / Boychisol</i>	
4. Generator's Phone () <i>950-2233</i>			
5. Transporter 1 Company Name	6. US EPA ID Number	A. State Transporter's ID	
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone <i>1800-837-8061</i>	
9. Designated Facility Name and Site Address <i>Waste Transfer Station 11000 Rd Dallas TX 75127</i>	10. US EPA ID Number	C. State Transporter's ID	
		D. Transporter 2 Phone	
		E. State Facility's ID	
		F. Facility's Phone	

11. WASTE DESCRIPTION	12. Containers No.	Type	13. Total Quantity	14. Unit Wt./Vol.
a. <i>11000 Rd Dallas TX 75127</i>	<i>100</i>	<i>CM</i>		
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above	H. Handling Codes for Wastes Listed Above <i>IN = 48,000 OUT = 38,600</i>
---	--

15. Special Handling Instructions and Additional Information

16. I, the undersigned, hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name	Signature	Date Month Day Year <i>8 10 15</i>
17. Transporter's Acknowledgment of Receipt of Materials	Signature	Date Month Day Year
18. Transporter's Acknowledgment of Receipt of Materials	Signature	Date Month Day Year
19. Discrepancy Indication Space		

20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name	Signature	Date Month Day Year <i>8 10 15</i>
--------------------	-----------	--