

Blue

GENERATOR (Generator completes I-a-f)

a. Generator's US EPA ID Number NA		b. Manifest Document Number 08-21-15-3541		c. Page 1 of 1	
d. Generator's Name and Location: Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone: (606) 775-9030			e. Generator's Mailing Address: Same		
g. Phone:			h. Owner's Name:		
i. Owner's Phone No.: Same			j. Waste Profile #		
k. Exp. Date 8/14/2017		l. Waste Shipping Name and Description Exploration and Production Soil and Debris		m. Containers No. Type 1 VB	n. Total Quantity 1
o. Unit 25 Yds					
GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.					
p. Generator Authorized Agent Name (Print) Craig Hiskens		q. Signature <i>[Signature]</i>		r. Date 7-28-15	

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: Salem Branch Transport		b. Phone: 571-115 TRUCK 571-60 TRAILER	
c. Driver Name (Print) Donald Love IV		d. Signature <i>[Signature]</i>	
e. Date 8-27-15			

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address: Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239		c. US EPA Number NA	d. Discrepancy Indication Space:
I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.			
e. Name of Authorized Agent (Print)		f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:		c. Responsible Agency Name and Address:	
b. Phone:		d. Phone:	
e. Special Handling Instructions and Additional Information: NA			
f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable			
OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.			
g. Operator's Name and Title (Print)		h. Signature	
i. Date			
*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both			

Beth Lowery

Blowery 8/27/15

White

I. GENERATOR (Generator completes Ila-f)				c. Page 1 of 1	
a. Generator's US EPA ID Number NA		b. Manifest Document Number 08-21-15-2			
d. Generator's Name and Location: Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone: (606) 776-9030			e. Generator's Mailing Address: Same		
g. Phone:			i. Owner's Phone No.: Same		
If owner of the generating facility differs from the generator, provide:					
h. Owner's Name:		k. Exp. Date		m. Containers	
j. Waste Profile #		i. Waste Shipping Name and Description		n. Total Quantity	
44002151		6/14/2017		1 VB	
		Exploration and Production Soil and Debris		1	
				25 Yds	
GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.					
p. Generator Authorized Agent Name (Print) Craig Hoskins		q. Signature [Signature]		r. Date 7-28-15	
II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)					
a. Transporter's Name and Address:					
b. Phone: 812-271-1515					
c. Driver Name (Print) Roderick Smith		d. Signature [Signature]		e. Date 8/27/15	
III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)					
a. Disposal Facility and Site Address: Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239		c. US EPA Number NA		d. Discrepancy Indication Space:	
I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.					
e. Name of Authorized Agent (Print)		f. Signature		g. Date	
IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)					
a. Operator's Name and Address:		c. Responsible Agency Name and Address:			
b. Phone:		d. Phone:			
e. Special Handling Instructions and Additional Information: NA					
f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable					
OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.					
NA		h. Signature		i. Date	
*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both					

Beth Lowery

Blowing 8/27/15

White Truck

I. GENERATOR (Generator completes Ia-r)

a. Generator's US EPA ID Number NA		b. Manifest Document Number 08-33-15-2		c. Page 1 of 1	
d. Generator's Name and Location: Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone: (606) 776-9030		e. Generator's Mailing Address: Same			
g. Phone:		i. Owner's Phone No.: Same			
h. Owner's Name:		If owner of the generating facility differs from the generator, provide:			
j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No. Type	n. Total Quantity	o. Unit Wt/Vol
44002151	6/14/2017	Exploration and Production Soil and Debris	1 VB	1	25 Yds
GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.					
p. Generator Authorized Agent Name (Print) Cory Haskins		q. Signature Cory Haskins		r. Date 7-28-15	

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: A Saluces Berach Transport			Load # 1 Trailer # 170		
b. Phone:			8/31/15		
c. Driver Name (Print) Rodney Smith		d. Signature Rodney Smith		e. Date	

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address: Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239		c. US EPA Number NA	d. Discrepancy Indication Space:
I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.			
e. Name of Authorized Agent (Print)		f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:		c. Responsible Agency Name and Address:	
b. Phone:		d. Phone:	
e. Special Handling Instructions and Additional Information: NA			
f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable			
OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.			
NA			
g. Operator's Name and Title (Print)		h. Signature	
		i. Date	
*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both.			

Both Lowary 8/31/15

I. GENERATOR (Generator completes Ia-f)

Blue truck

a. Generator's US EPA ID Number NA		b. Manifest Document Number <i>541 8-19-15-1</i>		c. Page 1 of 1	
d. Generator's Name and Location: Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone: (606) 776-9030			e. Generator's Mailing Address: Same		
g. Phone:			i. Owner's Phone No.: Same		
If owner of the generating facility differs from the generator, provide:					
h. Owner's Name:		k. Exp. Date 6/14/2017		i. Waste Shipping Name and Description Exploration and Production Soil and Debris	
j. Waste Profile # <i>Y4002151</i>				m. Containers No. Type 1 VB	
				n. Total Quantity 1	
				o. Unit Wt/Vol 25 Yds	

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print) <i>Greg Haskins</i>		q. Signature <i>[Signature]</i>		r. Date <i>7-28-15</i>	
---	--	------------------------------------	--	---------------------------	--

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: <i>S&P for BRANCH Transport TRUCK ST/115- TR. 1051/60</i>		
b. Phone:		
c. Driver Name (Print) <i>Ronald Howell</i>		d. Signature <i>[Signature]</i>
		e. Date <i>8-21-15</i>

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address: Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239		c. US EPA Number NA	d. Discrepancy Indication Space:
I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.			
e. Name of Authorized Agent (Print)		f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:		c. Responsible Agency Name and Address:	
b. Phone:		d. Phone:	
e. Special Handling Instructions and Additional Information: NA			
f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable			
OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.			
g. Operator's Name and Title (Print)		h. Signature	
		i. Date	
*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both			

Beth Lowery

Blowey 8/21/15

I. GENERATOR (Generator completes I(a-r))

a. Generator's US EPA ID Number NA		b. Manifest Document Number SAI 6-13-15-3		c. Page 1 of 1	
d. Generator's Name and Location: Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone: (606) 776-9030			e. Generator's Mailing Address: Same		
g. Phone:			i. Owner's Phone No.: Same		
h. Owner's Name:			j. Waste Profile #		
k. Exp. Date 6/14/2017		l. Waste Shipping Name and Description Exploration and Production Soil and Debris		m. Containers No. Type 1 VB	n. Total Quantity 1
o. Unit 25 Yds					

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print) C. Hork	q. Signature [Signature]	r. Date 7-28-15
---	-----------------------------	--------------------

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: Salyer Branch Transport Truck 115 IRA/OR		
b. Phone:	c. Driver Name (Print) Donald Lowe Jr	d. Signature [Signature]
e. Date 8-28-15		

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address: Blue Ridge Card F.I. 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239	c. US EPA Number NA	d. Discrepancy Indication Space:
I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.		
e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:		c. Responsible Agency Name and Address:	
b. Phone:		d. Phone:	
e. Special Handling Instructions and Additional Information: NA			
f. ☐ Friable ☐ Non-Friable ☐ Both		% Friable % Non-Friable	
OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.			
g. Operator's Name and Title (Print)		h. Signature	
i. Date			

*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both

Beth Lowery

Blowey 8/18/15

GENERATOR (Generator completes Ia-i)

a. Generator's US EPA ID Number NA		b. Manifest Document Number 8-11-15-2 SA1		c. Page 1 of 1	
d. Generator's Name and Location: Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone: (606) 776-9030			e. Generator's Mailing Address: Same g. Phone:		
If owner of the generating facility differs from the generator, provide:					
h. Owner's Name:			i. Owner's Phone No.: Same		
j. Waste Profile #	k. Exp. Date	l. Waste Shipping Name and Description	m. Containers No. Type	n. Total Quantity	o. Unit Wt/Vol
14002151	6/14/2017	Exploration and Production Soil and Debris	1 VB	1	25 Yds
GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.					
p. Generator's Authorized Agent Name (Print) Cory Hoshorn			q. Signature Cory Hoshorn		r. Date 7-28-15

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address: SALIX BRANCH TRANSPORT TANKS 51115 TRAIL 0257170		
b. Phone:		
c. Driver Name (Print) Donald Lovely	d. Signature Donald Lovely	e. Date 8-17-15

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address: Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239	c. US EPA Number NA	d. Discrepancy Indication Space:
I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.		
e. Name of Authorized Agent (Print)	f. Signature	g. Date

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:		c. Responsible Agency Name and Address:	
b. Phone:		d. Phone:	
e. Special Handling Instructions and Additional Information: NA			
f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable			
OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.			
g. Operator's Name and Title (Print)		h. Signature	
i. Date		8-17-15	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Nonhazardous</i>		Manifest Document No. 00878		2. Page 1 of	
3. Generator's Name and Mailing Address <i>Fairmont Wv 168 AFR OR Fairmont Wv</i>							
4. Generator's Phone (<i>606</i>) <i>776 9030</i>							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone <i>740 864 2137</i>			
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill 2700 Winchester Rd Irvine Ky</i>		10. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone <i>606 928 0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. <i>Exploration and Production Soil & Debris</i>				<i>001 UB TT</i>			
b. <i>Box # V10</i>							
c. <i>Y4002151</i>							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>Agent for Generator Raymond Bunner</i>				Signature <i>Raymond Bunner</i>		Date <i>11/13/15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Kevin Lucas</i>		Date <i>11/16/15</i>	
Printed/Typed Name <i>KEVIN LUCAS</i>							
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name							
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>K. R. H.</i>				Signature <i>K. R. H.</i>		Date <i>11/16/15</i>	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Non hazardous</i>		Manifest Document No. 00885		2. Page 1 of	
3. Generator's Name and Mailing Address <i>168 AFR DR Fairmont WV</i>							
4. Generator's Phone (<i>606</i>) <i>776 9030</i>							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
				B. Transporter 1 Phone <i>740 864 2131</i>			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill 2700 Winchester Rd Irvine Ky</i>		10. US EPA ID Number		E. State Facility's ID			
				F. Facility's Phone <i>606 928 0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No.	Type		
a. <i>Exploration and Production Soil & Debris</i>				<i>001</i>	<i>VB TT</i>		
b. <i>Box # V13</i>							
c. <i>Y4002151</i>							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>agent for Generator Raymond Bumer</i>				Signature <i>Raymond Bumer</i>		Date Month <i>11</i> Day <i>13</i> Year <i>15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Russ Country</i>		Date Month <i>11</i> Day <i>16</i> Year <i>15</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>Kim K...</i>				Signature <i>Kim K...</i>		Date Month <i>11</i> Day <i>16</i> Year <i>15</i>	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Non hazardous</i>		Manifest Document No. 00883		2. Page 1 of	
3. Generator's Name and Mailing Address <i>168 AFR Dr Fairmont WV</i>							
4. Generator's Phone (<i>606</i>) <i>776-9030</i>							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
				B. Transporter 1 Phone <i>740 864 2131</i>			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address <i>State Ridge Landfill 2700 Winchester Rd Irvine KY</i>		10. US EPA ID Number		E. State Facility's ID			
				F. Facility's Phone <i>606 928 0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		Unit Wt./Vol.	
a. <i>Exploration and Production Soil & Debris</i>				<i>001</i>		<i>VB TT</i>	
b. <i>Box # V16</i>							
c.							
d.							
G. Additional Descriptions for Materials Listed Above <i>Y4002151</i>				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>agent for Generator Raymond Bunner</i>				Signature <i>Raymond Bunner</i>		Date <i>11/13/15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name <i>agent for Generator Jeremy Scott</i>				Signature <i>[Signature]</i>		Date <i>11/13/15</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>Kim Kth</i>				Signature <i>[Signature]</i>		Date <i>11/13/15</i>	

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Non hazardous</i>		Manifest Document No. 00884		2. Page 1 of	
3. Generator's Name and Mailing Address <i>168 AFR CORP Fairmont WV</i>							
4. Generator's Phone (<i>606 776-9030</i>)							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone <i>740 864 2151</i>			
9. Designated Facility Name and Site Address <i>2700 Winchester Rd Irvine Ky</i>		10. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone <i>606 928 0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. <i>Exploration and Production Soil & Debris</i>				<i>001</i> <i>VB TT</i>			
b. <i>Box # V5</i>							
c. <i>Y 400251</i>							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>Cody Rummage</i>				Signature <i>[Signature]</i>		Date Month <i>11</i> Day <i>12</i> Year <i>15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name <i>Raymond Brunner</i>				Signature <i>Raymond Brunner</i>		Month <i>11</i> Day <i>12</i> Year <i>15</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name				Signature		Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.						Date	
Printed/Typed Name <i>Jim Rm</i>				Signature <i>[Signature]</i>		Month <i>11</i> Day <i>13</i> Year <i>15</i>	

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Nonhazardous</i>		Manifest Document No. 00880		2. Page 1 of	
3. Generator's Name and Mailing Address <i>1411 West 10th Ave Processing 1684 FR Dr Fairmont WV</i>							
4. Generator's Phone (606) <i>776 9030</i>							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
				B. Transporter 1 Phone <i>740 864 2137</i>			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill 2700 Winchester Rd Irvine Ky</i>		10. US EPA ID Number		E. State Facility's ID			
				F. Facility's Phone <i>606 928 0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		Unit	
a. <i>Exploration and Production Soil & Debris</i>				<i>VB</i>			
b. <i>Box # V 8</i>				<i>TT</i>			
c. <i># Y4002151</i>							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>agent for Generator Raymond Bumer</i>				Signature <i>Raymond Bumer</i>		Date <i>11/12/15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Kevin Lucas</i>		Date <i>11/12/15</i>	
Printed/Typed Name <i>Kevin Lucas</i>							
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name							
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>Jim Rahn</i>				Signature <i>Jim Rahn</i>		Date <i>11/12/15</i>	

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Nonhazardous</i>		Manifest Document No. 00832		2. Page 1 of	
3. Generator's Name and Mailing Address <i>168 AFR Dr Farming WU</i>							
4. Generator's Phone (606) <i>776 4030</i>							
5. Transporter 1 Company Name <i>Mountain States Environmental</i>		6. US EPA ID Number		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone <i>740 864 2137</i>			
9. Designated Facility Name and Site Address <i>Blue Ridge Landfill 2700 Winchester Rd Irvine Ky</i>		10. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone <i>606 928 0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. <i>Exploration and Production Soil & Debris</i>				<i>001 VB TT</i>			
b. <i>Box # V10</i>							
c. <i># Y 4002151</i>							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>Cody Rumsig</i>				Signature <i>[Signature]</i>		Date Month <i>11</i> Day <i>11</i> Year <i>15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name <i>Raymond Bunner</i>				Signature <i>Raymond Bunner</i>		Month <i>11</i> Day <i>11</i> Year <i>15</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name <i>Russ Courtney</i>				Signature <i>Russ Courtney</i>		Month <i>11</i> Day <i>12</i> Year <i>15</i>	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>Kim Ruth</i>				Signature <i>K. Ruth</i>		Date Month <i>11</i> Day <i>12</i> Year <i>15</i>	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>NON HAZARDOUS</i>		Manifest Document No. 00875		2. Page 1 of	
3. Generator's Name and Mailing Address <i>FAIRMONT BRINE 168 AFR OR. FAIRMONT W.V.</i>				TK#			
4. Generator's Phone (606) <i>776-9030</i>							
5. Transporter 1 Company Name <i>MOUNTAIN STATES ENV</i>		6. US EPA ID Number		A. State Transporter's ID			
				B. Transporter 1 Phone <i>740-864-2137</i>			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address <i>BLUE RIDGE LANDFILL 2700 WINCHESTER RD. IRVINE K.Y.</i>		10. US EPA ID Number		E. State Facility's ID			
				F. Facility's Phone <i>606-928-0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. <i>EXPLORATION AND PRODUCTION SAND & DEBRIS</i>							
b. <i>Box # V 16</i>							
c.							
d. <i>Y4002151</i>							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name <i>Agent for Generator Raymond Bunker</i>				Signature <i>Raymond Bunker</i>		Date Month <i>11</i> Day <i>11</i> Year <i>15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Bill Desrosiers</i>		Date Month <i>11</i> Day <i>11</i> Year <i>15</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature <i>Ken Ruten</i>		Date Month <i>11</i> Day <i>11</i> Year <i>15</i>	
Printed/Typed Name <i>Ken Ruten</i>				Signature		Date	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Base print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. NON Haz		Manifest Document No. 00864		2. Page 1 of 1	
3. Generator's Name and Mailing Address Fairmont Brink 168 AFR Dr Fairmont, WV				TR 550			
4. Generator's Phone (606) 776-9030							
5. Transporter 1 Company Name Mountain States Environmental		6. US EPA ID Number		A. State Transporter's ID			
				B. Transporter 1 Phone 740-864-2137			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address Blue Ridge Landfill 2700 Winchester Rd Irvine Ky		10. US EPA ID Number		E. State Facility's ID			
				F. Facility's Phone 606-928-0239			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No.	Type		
a. exploration and Production solids and debris							
b. Box # V-15							
c.							
d. Y4002151							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
AGENT FOR GENERATOR Printed/Typed Name: KEVIN LUCAS						Date: 11/6/15	
Signature: <i>Kevin Lucas</i>							
17. Transporter 1 Acknowledgement of Receipt of Materials						Date:	
Printed/Typed Name:						Month Day Year	
Signature:							
18. Transporter 2 Acknowledgement of Receipt of Materials						Date:	
Printed/Typed Name:						Month Day Year	
Signature:							
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in Item 19.							
Printed/Typed Name: Kim Roth						Date: 11/6/15	
Signature: <i>Kim Roth</i>							

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. NON HAZARDOUS		Manifest Document No. 00870		2. Page 1 of	
3. Generator's Name and Mailing Address FAIRMONT BRINE 168 AFR DR. FAIRMONT W.V.				TK 550			
4. Generator's Phone (606) 776-9030				A. State Transporter's ID			
5. Transporter 1 Company Name MOUNTAIN STATES ENV.				B. Transporter 1 Phone 740-864-2137			
7. Transporter 2 Company Name				C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address BLUE RIDGE LANDFILL 2700 WINCHESTER RD. ERVINE KY				E. State Facility's ID			
				F. Facility's Phone 606-928-0239			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. EXPLORATION AND PRODUCTION SAND & DEBRIS							
b. BOX V-16							
c.							
d. Y4002151							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name KEVIN LUCAS						Signature Kevin Lucas	
						Date Month Day Year 11 9 15	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name						Signature	
						Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name						Signature	
						Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in Item 19.							
Printed/Typed Name Belhewery						Signature Belhewery	
						Date Month Day Year 11 9 15	

NON-HAZARDOUS WASTE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>NON HAZARDOUS</i>		Manifest Document No. 00874	2. Page 1 of
3. Generator's Name and Mailing Address <i>FAIRMONT BRINE 168 AFR OR. FAIRMONT W.V.</i>				<i>TK #</i>	
4. Generator's Phone (<i>606</i>) <i>776-9030</i>					
5. Transporter 1 Company Name <i>MOUNTAIN STATES ENV.</i>		6. US EPA ID Number		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone <i>740-864-2137</i>	
9. Designated Facility Name and Site Address <i>BLUE RIDGE LANDFILL 2700 WINCHESTER RD. IRVINE K.Y.</i>		10. US EPA ID Number		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone <i>606-928-0239</i>	
11. WASTE DESCRIPTION				12. Containers	
				No.	Type
a. <i>EXPLORATION AND PRODUCTION SAND AND DERRIS</i>					
b. <i>Box # V-8</i>					
c.					
d. <i>Y4002151</i>					
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name <i>KEVIN LUCAS</i>				Signature <i>Kevin Lucas</i> Date Month <i>11</i> Day <i>11</i> Year <i>15</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name <i>Kim Rahn</i>				Signature <i>Kim Rahn</i> Date Month <i>11</i> Day <i>11</i> Year <i>15</i>	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>Non Haz</i>		Manifest Document No. 00863		2. Page 1 of 1	
3. Generator's Name and Mailing Address <i>Fairmont Brine 168 AFR Dr Fairmont WV</i>							
4. Generator's Phone (<i>606</i>) <i>776-9030</i>							
5. Transporter 1 Company Name <i>Mountain States Env.</i>		6. US EPA ID Number		A. State Transporter's ID			
				B. Transporter 1 Phone <i>740-864-2137</i>			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address <i>Blue ridge landfill 2700 Winchester Rd Irvine Ky</i>		10. US EPA ID Number		E. State Facility's ID			
				F. Facility's Phone <i>606-928-0239</i>			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. <i>Exploration and Production Soil and Debris</i>							
b. <i>Box # 17</i>							
c.							
d. <i>Y4002151</i>							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name				Signature		Date Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name <i>Russ Courtney</i>				Signature <i>Russ Courtney</i>		Month Day Year <i>11 4 15</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name				Signature		Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name <i>Kim Kish</i>				Signature <i>Kim Kish</i>		Date Month Day Year <i>11 4 15</i>	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

White truck

I. GENERATOR (Generator completes Ia-r)

a. Generator's US EPA ID Number NA		b. Manifest Document Number 8-18-15-2		c. Page 1 of 1	
d. Generator's Name and Location: Fairmont Brine 168 AFR Dr Fairmont, WV f. Phone: (606) 776-9030			e. Generator's Mailing Address: Same		
g. Phone:			i. Owner's Phone No.: Same		
If owner of the generating facility differs from the generator, provide:					
h. Owner's Name:		k. Exp. Date		l. Waste Shipping Name and Description	
j. Waste Profile #		6/14/2017		Exploration and Production Soil and Debris	
Y4002151				1 VB 1 25 Yds	

GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations; AND, if this waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal Restrictions. I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR 268 and is no longer a hazardous waste as defined by 40 CFR 261.

p. Generator Authorized Agent Name (Print) C. H. H. H.		q. Signature C. H. H. H.		r. Date 7-28-15	
---	--	-----------------------------	--	--------------------	--

II. TRANSPORTER (Generator completes IIa-b and Transporter completes IIc-e)

a. Transporter's Name and Address:			# 168		
b. Phone:			Salvors Branch Transport		
c. Driver Name (Print) Rodney Smith			d. Signature Rodney Smith		
			e. Date 8/20/15		

III. DESTINATION (Generator complete IIIa-c and Destination Site completes IIId-g)

a. Disposal Facility and Site Address: Blue Ridge Landfill 2700 Winchester Rd Irvine, Ky b. Phone: 606 928 0239		c. US EPA Number NA		d. Discrepancy Indication Space:	
I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate.					
e. Name of Authorized Agent (Print)		f. Signature		g. Date	

IV. ASBESTOS (Generator completes IVa-f and Operator complete IVg-i)

a. Operator's Name and Address:		c. Responsible Agency Name and Address:	
b. Phone:		d. Phone:	
e. Special Handling Instructions and Additional Information: NA			
f. ☐ Friable ☐ Non-Friable ☐ Both % Friable % Non-Friable			
OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.			
NA			
g. Operator's Name and Title (Print)		h. Signature	
		i. Date	
*Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation or both			